


VACUUM PACKAGING MACHINE
MODEL 680A



OWNERS MANUEL
(MANUEL D'UTILISATION)
(MANUAL DE UTILIZACION)

IMPORTANT SAFETY INSTRUCTIONS

SAVE THESE INSTRUCTIONS



This symbol points out important safety instructions which, if not followed, could endanger the personal safety and/or property of yourself and others. Read and follow all instructions in this manual before attempting to operate your machine. Failure to comply with these instructions may result in personal injury.

General Operation

- Read, understand, and follow all instructions in the manual and on the machine before starting. Keep this manual in a safe place for further and regular reference and for ordering replacement parts.
- Only allow responsible individuals familiar with the instructions to operate the machine. Be sure to know controls and how to stop the machine quickly.
- Never put your hands near moving parts.
- Only allow qualified individuals for the maintenance of your machine.
- Remove all obstacles, which may interfere with the machine functions.
- Clear the work area such as electrical wires, buckets, knives etc.
- Be sure that everyone else is clear of your work area before operating the machine.
- Do not sit nor stand on the machine.
- Always turn off the machine after your work is done. Never leave a running machine unattended.
- Always disconnect and wait till the machine has cooled before attempting any maintenance.
- Do not wear loose fitting clothes or jewelry as they may get caught in moving parts of the machine.
- Always wear security shoes, to prevent injury caused by moving the machine or objects falling from the machine.
- Never exceed the time limit to seal, which is recommended by the manufacturer. This is to avoid any damage that may be caused to the sealing bars and to eliminate the risk of fire in the machine. Thus avoiding corporal burns.
- Never touch the sealing bars after they have been used, this will avoid corporal burns. Wait a few minutes to let the machine cool down before touching.
- Always make sure that the sealing bars are well installed in their "Guide Blocks" before starting a cycle.
- Never incline the machine more than 30 degrees, it may tip over and hurt someone seriously.
- Work only in daylight or good artificial light.

Do not operate the machine while under the influence of alcohol or drugs!

Service

- Use proper containers when draining the oil. Do not use food or beverage containers that may mislead someone into drinking from them. Properly dispose of the containers, or store in a safe place immediately following the draining of the oil.
- Prior to disposal, determine the proper method to dispose of waste from your local office of Environmental Protection Agency. Recycling centers are established to properly dispose of materials in an environmentally safe fashion.

Do not pour oil or other fluids into the ground, down a drain or into a body of water.



Warning-Your responsibility:

This machine should only be operated by personal who can read, understand and respect warnings and instructions regarding this machine in the owners manual. Save these instructions for future reference.

VACUUM PACKAGING MACHINE

MODEL 680A

(MC-40 SIPROMAC)

GENERAL TABLE OF CONTENTS

I OPERATION INSTRUCTIONS

II MECHANICAL

- A- Front view general assembly drawing
- B- Rear view general assembly drawing
- C- Cover adjustment procedure
- D- Central shaft assembly drawing
- E- Seal bar assembly drawings
(twin seal)
- F- Seal bar assembly drawings
(electrical bag cut option)
- G- Seal bar assembly drawings
(top and bottom sealing option)
- H- Gas injection kit installation drawing
(gas injection option)

III ELECTRICAL

- A- Electrical drawings

IV PNEUMATIC

- A- Pneumatic drawing

VACUUM PACKAGING MACHINES

OPERATION INSTRUCTIONS

TABLE OF CONTENTS

1. Setting up the machine
2. Electrical connection
3. Operation
 - 3.1 Working principles
 - 3.2 Special packaging
 - 3.2.1 Gas flushing
 - 3.2.2 Top and bottom sealing (bi-active)
 - 3.2.2 3.2.3 Electrical bag cut
 - 3.3 Setting of digital controls
 - 3.4 Daily cleaning
4. Trouble shooting
 - 4.1 Failure during a packaging cycle
 - 4.2 Insufficient vacuum
 - 4.2.1 Leakage in the bag
 - 4.2.2 No leakage in the bag
 - 4.2.3 Insufficient vacuum in the chamber
 - 4.3 Faulty seal
 - 4.3.1 Insufficient seal
 - 4.3.2 No seal
 - 4.3.3 Permanent sealing current
 - 4.3.4 Seal does not stick
 - 4.4 Fault in the valves
 - 4.5 Control board failure
5. Regular maintenance

2010-08-30

SIPROMAC INC. VACUUM PACKAGING MACHINES

1. SETTING UP THE MACHINE:

Before choosing the site for the machine, please consider that you will also need room for packaged and non-packaged products apart from the space needed for the machine itself.

Keep in mind that the machine must not be set up upon uneven ground. Especially with mobile models, the weight of the pump might then cause warping of the machine. Then the lid will not fit correctly.

Before starting to work, check the oil view glass on the pump, if there is a sufficient quantity of oil in the pump. Never use oil other than recommended by the producer. Never exceed maximum quantity of oil indicated, when adding or changing oil. Verify weekly.

Normal ambient temperature for the vacuum pump is between 10 to 70°C. For temperature below 10°C; it is recommended to use synthetic oil. Please consult factory and pump manufacturer manual for more information or when ambient temperature are outside normal limits

2. ELECTRICAL CONNECTION:

Electrical connections must be made by qualified personnel. This person must make sure that the electrical entries corresponds to the proper voltage and amperage of the machine. **GROUNDING INSTRUCTIONS:** This appliance must be connected to a grounded, metal, permanent wiring system; or an equipment-grounding conductor must be run with the circuit conductors and connected to the equipment-grounding terminal or lead on the appliance. A qualified electrician should be consulted if there is any doubt as to whether an outlet box is properly grounded.

All vacuum machines are supplied with an electrical schematic drawing. An important step in connecting the machine is to make sure that the pump turns in its correct rotation.



The pump should not rotate more than 3 to 4 seconds in the wrong rotation or it may cause serious damage. The proper rotation is indicated by an arrow on the pump motor.

3. OPERATION:

3.1 Working principles:

A vacuum packaging cycle is made of 3 stages. First the vacuum is made, the air is completely taken out of the chamber and from bag containing the product. (See figure 1). Then it is possible to inject neutral gas from the nozzles, if the product is delicate. Finally, a mechanism pushes the sealing bar to the rubber support to seal the bag.

To obtain nice packages, the products and the bags have to be of proportional sizes. The bag's opening should never exceed 50 cm(2") past the seal bars. The product should be centered in height in relation to the seal bar by adjusting the spacers provided.

To obtain a good seal, make sure that no residue of fat is left between the bag's inner sides where sealing is done.




FIGURE 1

3.2 Special packaging:

3.2.1 Gas flushing (option):

There is an atmospheric pressure of 1 kg/ sq. cm (14 lbs/sq. inch) upon products when fully evacuated. Products which can be damaged by high pressure must be packaged with a partial vacuum, or the pressure must be counterbalance by inflating the bag with gas (nitrogen or carbon dioxide) before sealing after evacuation.

For gas flushing, the bags are placed on the sealing bars, the open end placed over the gas nozzles mounted alongside the sealing bar. After evacuation, the vacuum valve closes and the gas valve opens. Gas time (sec.) can be set in the program menu.

The necessary gas tank and pressure valve mounted on tank is not supplied, The pressure of the gas regulator should be set at approximately 1/3 kg/sq. cm (5 lbs/sq.inch.). Each machine has an adaptor for gas connection when gas flush option is ordered.

3.2.2 Top and bottom sealing (optional):

When sealing aluminium laminate bags (especially bags for e.g. coffee) it is imperative to have an upper and a lower sealing bar.

3.2.2 Electrical bag cut (optional):

This option is used to obtain a package that the excess bagtail is cut off close to the seal (cannot be used with top and bottom sealing).

3.2.3 Select operating mode

When executing the "select operating mode" function, which is available only for the automatic units, the actual selection is blinking to point out the acquisition mode. Use key "SELECT" to get through the operating modes, which are automatic, semi-automatic and manual; the validation of the selected operating mode is performed automatically. Use key "ESC" or "ENTER" to leave the function and get back to the program menu.

3.3 Vacuum packaging operation:

3.3 Vacuum packaging operation:

Note: Refer to the menus structure on page 14 and the keyboard detail on page 15.

3.3.1 Basics:

Use key "POWER" to power ON / OFF the vacuum packaging machine. When the unit is energized, the identification of the last executed program is displayed on LCD screen.

Use the "ESC" key to change over from the programs menu to the functions menu and from the functions menu to the programs menu.

In functions menu, use key "SELECT" to select a function and key "ENTER" to accede and executed the selection.

In programs menu, use key "SELECT" to select a program and key "ENTER" to accede and modify the selection.

In programs submenu, use key "ENTER" to pass over the parameters and point to the following one; the parameters are blinking to point out the acquisition mode. A return to programs menu is performed automatically following the last parameter acquisition.

In program submenu, use key "ESC" to get back to the programs menu. Strike any key to clear the error messages which may be displayed on LCD screen.

3.3.2 Functions:

3.3.2.1 Create a program:

When executing the "create a program" function, the program submenu is acceded, starting with the identification. The initial identification "Pxx NO NAME" is given to the program and all parameters are established to zero; the program number is allocated automatically.

3.3.2.2 Delete a program:

When executing the "delete a program" function, the programs menu is acceded and the number of the first program in memory is blinking to point out the deletion mode. Use key "SELECT" to select a program and key "ENTER" to accede and confirm deletion of the selection. Use key "ESC" to unconfirm a deletion and to leave the function. When leaving the function, the number of the

actual program on LCD screen cease to blink.

3.3.2.3 Select operating mode:

When executing the "select operating mode" function, which is available only for the automatic units, the actual selection is blinking to point out the acquisition mode. Use key "SELECT" to get through the operating modes, which are automatic, semi-automatic and manual; the validation of the selected operating mode is performed automatically. Use key "ESC" or "ENTER" to leave the function and get back to the program menu.

3.3.3 Programs menu:

3.3.3.1 Program identification:

For a selected program, set the identification, using the numeric keyboard characters chart; press numeric key until the desired character is selected (4 times for the numeric value). Use key "ENTER" to validate the character and to validate the characters string at the end (the new characters string is blinking). In a middle of an acquisition, use key "ESC" to come backward and erase one or several characters.

Example: EXAMPLE 1 → (9 characters)	keys 2, 2, ENTER	→ E
	keys 8, 8, 8, ENTER	→ X
	keys 1, ENTER	→ A
	keys 5, ENTER	→ M
	keys 6, ENTER	→ P
	keys 4, 4, 4, ENTER	→ L
	keys 2, 2, ENTER	→ E
	keys 9, 9, 9, ENTER	→ space
	keys 1, 1, 1, 1, ENTER	→ 1
	key ENTER to validate the characters string	

3.3.3.2 Vacuum level setting:

For a selected program set the vacuum level, starting with the values; the decimal point is automatically inserted following the second digit entry and the validation is automatically performed following the third digit entry (the new vacuum level is blinking). The vacuum level is rounded off to the nearest half value. In the middle of an acquisition, use key "ENTER" to validate the vacuum level and key "ESC" to come backward and start over with a new acquisition (the old vacuum level is blinking). Set vacuum level to zero to bypass the pressure transducer and proceed only using the vacuum plus time.

Examples: 90.0% → keys 9, 0, 0 or 9, 0, ENTER or
 keys 9, 0, 1 or 9, 0, 2 or 9, 0, 3 or 9, 0, 4
97.5% → keys 9, 7, 5 or
 keys 9, 7, 6 or 9, 0, 7 or 9, 0, 8 or 9, 0, 9
0.0% → keys 0, 0, 0 or 0, ENTER

3.3.3.3 Vacuum plus time setting:

For a selected program set the vacuum plus time, in seconds; the validation is automatically performed following the second digit entry (the new vacuum plus time is blinking). In a middle of an acquisition, use key "ENTER" to validate the vacuum plus time and key "ESC" to come backward and start over with a new acquisition (the old vacuum plus time is blinking).

Examples: 1s → keys 0, 1 **or** 1, ENTER
 15s → keys 1, 5

3.3.3.4 Gas flush level setting:

For a selected program set the gas flush level following the same procedure as for the vacuum level; the maximum gas flush level setting is 10% below the vacuum setting.

3.3.3.5 Sealing time setting:

For a selected program set the sealing time, starting with the seconds; the decimal point is automatically inserted following the first digit entry and the validation is automatically performed following the third digit entry (the new sealing time is blinking). The sealing time is truncated to the nearest half hundredth. In a middle of an acquisition, use key "ENTER" to validate the sealing time and key "ESC" to come backward and start over with a new acquisition (the old sealing time is blinking).

Examples: 4.50s → keys 4, 5, 0 or 4, 5, ENTER or
keys 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
2.35s → keys 2, 3, 5 or
keys 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
0.00s → keys 0, 0, 0 or 0, ENTER

3.3.4 Vacuum cycle execution:

For the manual units and the automatic units set on manual, close the cover to initiate a vacuum cycle. For the automatic units set on semi-automatic or on automatic, use push button "STOP / START" to initiate or interrupt a vacuum cycle. A selected program can be initiated only in the programs menu, when no modifications are in progress, and the access to the other programs and functions is denied. During cycle execution the operation status is sequentially displayed on LCD screen, except for the parameters established to zero, which are not displayed:

- chamber vacuum level during vacuum sequence,
- vacuum plus time status during vacuum plus sequence,
- chamber vacuum level during gas flush sequence,
- sealing time status during sealing sequence,
- chamber vacuum level during atmosphere sequence.

During cycle execution, use key "1" to abort the vacuum sequence and execute the following sequence, which is gas flush or sealing, and key "ENTER" to accede and modify the program; the parameters become valid only for the following vacuum cycles.

3.3.5 System monitor:

To accede the diagnostics menu, power up the vacuum packaging machine while keeping pushed in the "ESC" key. Use key "SELECT" to select the system monitor function and key "ENTER" to accede and visualize the monitored parameters. Use key "SELECT" to change over from the software revision, the amount of working hours done and the amount of complete cycles performed since first initialization.

-MENUS STRUCTURE-

- **Functions menu:**

"F1 CREATE A PRGM"

"F2 DELETE A PRGM"

"F3 SELECT OPMODE" (automatic units only)

- **Programs menu:**

"Pxx NAME"

Program submenu:

"VACUUM: xx.x%" (10.0% - 99.5%)

"VACUUM PLUS: xxs"(0s - 99s)

"GAS FLUSH: xx.x%" (0.0% - 10% below the vacuum level) (units with gas option)

"SEAL TIME: x.xxs" (0.00s - maximum unit allocated setting)

"Pxx NAME" (12 characters)

- **Diagnostics menu** (keys "ESC" & "POWER" for access):

"DIAGNOSTICS MENU" (access code required)

"D1 INPUTS TEST"

"D2 OUTPUTS TEST"

"D3 MODEL SELECT"

"D4 GAS OPTION"

"D5 SEALING TIME"

"D6 COOLING TIME"

"D7 OFFSET CALIB."

"D8 VACUUM SENSOR"

"D9 SIPROMAC PUB"

"D10 LOADING TIME" (automatic units only)

"D11 UNLOADNG TIME" (automatic units only)

"SYSTEM MONITOR" (no access code required)


"SOFTWARE: R x.xx"

"WORK HRS: xxxxx"

"CYCLES: xxxxxxxx"

-KEYBOARD DETAILS-

MC-40 CONTROLS





WARNING: All electrical work described in this brochure should be done by a QUALIFIED and AUTHORIZED technician.

3.4 Daily cleaning:

For hygienic cleanliness, it is imperative to clean chamber and spacers daily. Also clean the lid rubber to assure tight seat of the lid.

Cleaning instructions for gas injection nozzles: Periodically on a regular basis the gas injection nozzles must be removed with the connection tube and soaked in a food grade soap and water solution, then dried and re-installed.

4. TROUBLE SHOOTING:

4.1 Failure during packaging cycle:

4.1.1 "VACUUM ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the vacuum sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.2 "GAS FLUSH ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the gas flush sequence within a preset period of time.

- Check gas flush and vacuum lines for potential leaks or kinks.

4.1.3 "ATMOSPHERE ERROR" message is displayed on LCD:

No pressure variation is picked up by the PCB transducer during the atmosphere sequence within a preset period of time.

- Check vacuum lines for potential leaks or kinks.

4.1.4 "COVER DOWN ERROR" message is displayed on LCD(manual units):

The input signal of the down position switch has been lost during cycle execution.

- Check limit switch adjustment.

4.2 Insufficient vacuum:

4.2.1 Leakage in the bag:

Most frequently, insufficient vacuum in bags is due to leakage in bag and not due to any fault of the machine.

Pin-hole leak for which there is no obvious explanation is due to faulty bag material.

Pin-hole leak caused by sharp edge of the product (bone, etc.). Use bone-guard or thicker film.

Tear in bag by careless handling (sharp edge on filling table, damage made by retailer or customer).

Leakage in lateral or bottom seal, complain to supplier of bags or film.

4.2.2 No leakage in the bag:

Bag is too large, therefore the surplus of air remains visible (there is surplus of air in 0.4% of the bag volume in each bag). Use bags of suitable size.

Vacuum level is too low:

Pressure bar is jammed and closes opening of bag during evacuation.

4.2.3 Insufficient vacuum in chamber:

If troubles described under 4.2.1 and 4.2.2 do not apply, there is something wrong with the evacuation. To find the leakage quickly, check for leaks with a precision vacuumeter, going back step by step from the chamber to the pump.

At the chamber (measuring point at base of valve) at maximum time of evacuation. If more than 6 torr, proceed directly to the pump, if more than 3 torr: have pump service by pump supplier. If pressure at pump is good, reconnect hoses to pump and measure again.

Verify at vacuum hose connections and valve connections.

When proceeding this way, starting from pump, loss of pressure per step must not exceed 0.5 to 1 torr.

Caution: Verify connections of measuring equipment before verifying machine.

Most frequent points of leakage: lid gasket, damaged vacuum hose or loose hose clamps.

4.3 Faulty seal:

4.3.1 Insufficient seal:

Damaged teflon or silicone rubber.

Sealing pressure too low, bellows leaking or pressure bar jammed.

Leakers in seal: heating wire mechanically damaged (knicked) or silicone rubber uneven.

4.3.2 No seal:

Sealing wire burnt.

Faulty contact in sealing circuit.

Sealing transformer burnt through.

Contactors does not work.

4.3.3 Permanent sealing current:

Contactors is jammed check sealing transformer for damage through overload.

4.3.4 Seal does not stick:

Insufficient layer of polyethylene (inferior quality of bags).

Seal area extremely contaminated by fat or meat juice. Use filling aid.

Sealing temperature is too low (when using very thick films).

Caution: Do not increase sealing time more than really necessary; higher temperature will reduce working life of teflon and silicone rubber.

4.4 Fault in the valve:

Vacuum or air valve does not open.

Check whether there is voltage on the magnetic valves during their period of operation. If there is no voltage a wire is broken or the PC board is damaged.

Lid does not open at the end of the cycle; air enters, but there is still 20 - 40% vacuum in chamber. Vacuum valve does not close.

4.5 MC40 Control board failure

NOTE: Refer to menu structure on page 13.

This board software is allowing access to a "Diagnostics Menu". Only qualified service technicians are authorized to access this menu by entering a security password.

By acceding either the "D1 input test" feature or the "D2 output test" feature, a trained technician will be able to quickly know the origin of the problem: pump, sealing system, pneumatic problem, security switches problem, etc...

Keep in mind that in most cases trouble is due to a leakage, loose electrical connection or evident damage to the main components: vacuum pump, valves, electrical contactors, thermal overload, fuses holder or transformer.

For assistance do not hesitate to contact your local service technicians.

5. Regular maintenance:

Routine controls to be made at regular intervals:

Check teflon for wear.

Check silicone rubber for burnt spots and smooth even position.

Check pressure bar for jamming.

Check lid sealing for damage and hardened spots.

Check switch-point of micro switch, adjust if necessary.

Check evacuation hose for damage (contraction of diameter, or abrasions).

Check vacuum connections for tightness.

Check oil in pump (oil level in view glass; add if necessary. Regular change of oil - necessity indicated by change of color).

Check vacuum in chamber with precision vacuumeter.

Check function of cycle with various settings of timers.

680A

OPERATING GUIDE

- 1 st Push **POWER ON**.
- 2 nd Adjust vacuum level, gas level and seal time, if or as needed (refer to sec. 3.3).
- 3 rd Select manual, semi-automatic or automatic mode.
- 4 th Place the chamber half way down on one side (left or right).
IMPORTANT: Never push start when the chamber is in the middle.
- 5 th Place products on the opposite side.
- 6 th To change vacuum level, gas level or seal time, push stop button before attempting to change.
- 7 th When the machine is stopped during a vacuum cycle, the ON/OFF button must be pressed, then the start button to be able to re-start the machine.

MACHINE SHOULD BE **STRAIGHT** & **LEVEL**


HOW TO ADJUST SPEED OF COVER

- 1 st Machine should be level (adjustable feet)
- 2 nd Put machine in automatic mode, vacuum time 99.5%.
Adjust cylinder pressure regulator at 80 PSI.
- 3 rd Bring cover close to the table, start machine and adjust the exhaust flow control on the lifting solenoid valve (See drawing #007-0039) to the desired speed.
- 4 rd Adjust the exhaust flow control on the chamber lowering solenoid valve (turning screw clockwise will reduce the speed).


MACHINE STOPPED WITH CHAMBER UNDER VACUUM:

HOW TO RE-START THE MACHINE:

- 1 st Press on/off switch on the membrane to stop the machine.
- 2 nd Press on/off again to re-start the machine (vacuum valve will open and machine will continue its cycle).
- 3 rd Press start to have the automatic movement of cover.




MECHANICAL DRAWING



1005A0438

ITEM	PART #	DESCRIPTION	QT.	ITEM	PART #	DESCRIPTION	QT.
49	104-00633	SILICONE TUBING 1/2" OD X 1/4" ID 70 DURO (5 FT)	1	1	030-0720	SHRINK BLACK 1-1/2" x 24mm (0.0827 EACH)	4
50	004-0401	TABLE END SECURITY PRE-ASSY	2	2	004A0239	TABLE & CENTRAL SHAFT ASSY	1
51	058-0025	NYLON SPACER 0.257" ID x 0.500" OD x 1/4"	1	3	004A0381	COVER ARM ASSY	4
52	105-00450	METAL CABLE CLAMPS #6 SS	1	4	005-0472	STRUCTURE ASSY	1
53	101-0200	STRAIGHT 1/4" MNPT x 1/4" HOSE BARB	1	5	005-0362	REAR LEG ASSY	1
54	105-0220	EAR CLAMP 1/2"	3	6	005-0469	8" COVER ASSEMBLY	1
55	051-0233	SCREW 1/4-20 X 1-1/4" PAN PHIL S/S	1	7	005-0359	ARM SUPPORT ASSEMBLY	2
56	057-0089	1/4" x 5/8" O.D. EPDM RUB. SEAL, WASHER	4	8	005-0361	FRONT LEG ASSY	2
				9	008-0368	ARM SUPPORT SPACER	4
				10	004-0213	COVER HANDLE ASSY	2
				11	051-0630	NUT 1/2"-13 S/S	4
				12	005-0617	COVER GUARD ASSEMBLY	1
				13	003B0126	JUNCTION BOX (LEFT)	1
				14	056-0125	HITCH PIN CLIPS 3mm X 60mm S/S	1
				15	051-0600	NUT 5/16"-18 S/S	20
				16	004A0447	JUNCTION BOX ASSY (RIGHT)	1
				17	051-0305	BOLT 5/16"-18 NC X 1" S/S	2
				18	002-0326	LEFT SEAL BAR GUIDE BLOCK	4
				19	003-0107	SECURITY BUMPER HOLDER 500	8
				20	002-0327	RIGHT SEAL BAR GUIDE BLOCK	4
				21	051-0740	WASHER 1/4" FLAT S/S	38
				22	001-0892	SEAL BAR GUIDE BLOCK SPACER	1
				23	051-0250	BOLT 1/4"-20nc. X 1 1/2" S/S	16
				24	051-0581	NUT 1/4"-20 NYLON LOCK S/S	16
				25	057-0013	SHAFT END CAP 1-1/4"	4
				26	005A0549	SEAL BAR ASSY W/SUPP. (TOP & BOT. OPT.)	1
				27	005-0470	12" COVER ASSEMBLY (OPT)	1
				28	005A0548	SEAL BAR ASSY W/ SUPP. (BAG CUT. OPT.)	1
				29	005-0651	BELLOWS ASSEMBLY	3
				30	005A0547	SEAL BAR ASSY W/ SUPPORT	4
				31	005-0349	FILLER PLATE ASSEMBLY	2
				32	005A0350	GAS INJECTION BAR ASSEMBLY	2
				33	005A0814	GAS INJECTION BAR ASSEMBLY	1
				34	056-0167	KEY 1/4"x1" OVERSIZED	4
				35	005A0392	FRONT PC BOARD SUPPORT ASSY	1
				36	052-0045	FLAT WASHER 1/4" COPPER	4
				37	051-0591	NUT 1/4"-20 ACORN S/S	4
				38	105-0430	SCREW COLLARD 3/4" x 1 1/4" x 9/16" S/S	4
				39	051-0783	WASHER 3/8" FLAT THICK S/S	4
				40	051-0422	BOLT 3/8"-16nc. X 3/4" S/S	2
				41	051-0822	NUT 3/8"-16nc. NYLON LOCK S/S	2
				42	003-0107	SECURITY BUMPER HOLDER 500	9
				43	051-0097	SCREW 6-32 x 3/8" TYPE F PAN PHIL S/S	24
				44	051-0760	WASHER 5/16" FLAT S/S	32
				45	051-0300	BOLT 5/16"-18nc. X 3/4" S/S	16
				46	008-0464	GAS INJECTION CONNECTION TUBE	4
				47	051-0192	SCREW 1/4-20NC X 3/4" PAN PHIL S/S	8
				48	051-0190	BOLT 1/4-20 x 3/4" HEX S/S	6



DETAIL A

NOTE:

-FOR GAZ INJECTION
KIT INSTALLATION
SEE DRAWING #010-0020

33 32

46

26 28 30

7

15

42

21

20

22

23

24

21

20

21

20

21

20

21

20

21

20

21

20

21

20

21

20

21

20

21


20

21

20

21


DETAIL B



MACHINE		680A		SIPROMAC		ST-JERMAIN DE GRANTHAM		QUEBEC CANADA	
PART		MACHINE ASSEMBLY FRONT VIEW		N.T.S.		DEPT. 1		QTY. 1	
ITEM		DATE 04-08-27		DATE 04-08-27		DATE 04-08-27		DATE 04-08-27	
JAT.		B.C.		B.C.		B.C.		B.C.	
MODIFIED VIEW ITEM 4 & 35, ADDED PART 057-0089		05-08-11		05-08-11		05-08-11		05-08-11	
ADDED PARTS #48 TO #55		04-11-18		04-11-18		04-11-18		04-11-18	
REDRAWN		04-08-27		04-08-27		04-08-27		04-08-27	
MODIFICATION		DATE		DATE		DATE		DATE	
INT.		INT.		INT.		INT.		INT.	

005A0438

ITEM	PART #	DESCRIPTION	QTY.
1	005-0438	MACHINE ASSEMBLY FRONT VIEW	1
2	051-0350	HEX. BOLT 3/8"-16 x 3/4" S.S.	10
3	051-0780	FLAT WASHER 3/8" S.S.	44
4	051-0620	HEX. NUT 3/8"-16 S.S.	22
5		REAR SPACER	2
6	008-0368	SPACER	2
7	002A0361	COVER ARM	2
8	075-0620	BUSHING	2
9	105-0430	COLLAR	2
10	051-0520	SET SCREW 5/16"-18 x 3/8" S.S.	2
11	051-0420	HEX. BOLT 3/8"-16 x 3/4" S.S.	2
12	051-0783	FLAT WASHER 3/8" (THICK) S.S.	4
13	057-0013	SHAFT END CAP	2
14	005-0401	ELECTRICAL BOX ASSEMBLY	1
15	004-0218	FALSE BOTTOM ELECTRICAL BOX	1
16	051-0210	HEX. BOLT 1/4"-20 x 1" S.S.	6
17	051-0740	FLAT WASHER 1/4" S.S.	16
18	051-0580	HEX. NUT 1/4"-20 S.S.	18
19	001-1545	ELECTRICAL BOX COVER	1
20	179-0004	SELFSTICK NEOPRENE	1
21	051-0180	HEX. BOLT 1/4"-20 x 1 1/2" S.S.	4
22	004-0191	BEAM MOVEMENT ASSEMBLY	1
23	004-0192	ARM AXIS MOVEMENT ASSEMBLY	2
24	056-0120	COTTER PIN 1/8" Ø x 1" S.S.	4
25	003A0180	CYLINDER REWORKED	1
26	051-0645	HALF NUT 1/2"-20 UNF S.S.	1
27	002-0387	CYLINDER EXTENSION	1
28	058-0060	SPACER	1
29	058-0050	SPACER	5
30	004-0193	UPPER CYLINDER AXIS ASS'Y	1
31	004-0205	CYLINDER SUPPORT ASSEMBLY	1
32	004-0947	CYLINDER SUPPORT REINFORCEMENT	2
33	051-0360	HEX. BOLT 3/8"-16 x 1" S.S.	12
34	002A0388	CYLINDER AXIS	1
35	051-0675	HEX. NUT 3/4"-10 S.S.	2
36	005-0354	PUMP SUPPORT ASSEMBLY	2
37	005-0088	PUMP SUPPORT	6
38	125-	PUMP 160 M ³ (OPTION)	1
39	125-	PUMP 250 M ³ (OPTION)	1
40	001-0199	SUPPORT	4
41	052-4240	HEX. BOLT M10 x 30 S.S.	4
42	003-0083	ELBOW BELLOW CONNECTOR	1
43	004-0505	VACUUM/ATMOSPHERE VALVE ASS'Y	1
44	051-0380	HEX. BOLT 3/8"-16 x 1 1/2" S.S.	2
45	101-0190	STRAIGHT 1/8" MNPT x 1/4" HOSE	2
46	056-0167	KEY 1/4" SQ x 1" W/ ROUNDED END	4
47	052-0402	HEX. BOLT 1/4"-20 x 1 1/2" BRASS	4




MACHINE		680A	
PART		MACHINE ASSEMBLY REAR VIEW	
ITEM:	QTY:	DATE:	SCALE:
005A0439	1	99-11-29	1
BY: SYLVAIN L.		DATE:	
APP:		DATE:	

MOD.	DATE	Y.C.
D. MODIF. #A-0337	02-11-06	S.L.
C. REDRAWN/ ADD KEYWAY ON COVER ARM	99-11-29	S.L.
B. CHANGE PIPE ON ITEM #42 FOR ITEM #47	99-04-07	S.L.
A. WAS 004-0217 / MODIF. #A-0281	98-01-15	M.L.
LET.	DATE	INT.


1004A0239

SPRING ADJUSTMENT PROCEDURE

- A - PLACE COVER UP (ARMS VERTICAL) TO FREE TENSION OF SPRINGS.
- B - LOOSEN BOLTS ITEM #10 ON THE LEFT & RIGHT SPRING SUPPORT PLATE ASSY ITEM #4 & #5
- C - TURN SPRING/BLOCK ASSEMBLY TO OBTAIN 0mm AS SHOWN BELOW.





- D - RETIGHTEN BOLTS ITEM #10 ON LEFT & RIGHT SPRING SUPPORT PLATE ASSY



IF THE END OF THE SPRING HAS A 90° CORNER AS SHOWN,
THIS END IS TO BE INSERTED INTO ITEMS #4 & #5


ITEM	PART #	DESCRIPTION	QT.
1	005-0436	TABLE ASSEMBLY	1
2	009A0054	CENTRAL SHAFT	2
3	002A0319	SPRING BLOCK	4
4	004A0222	LEFT SPRING SUPPORT ASSY	2
5	004A0170	RIGHT SPRING SUPPORT ASSY	2
6	056-0168	KEY 1/4" SQ. x 1-1/2"	4
7	052-2060	FLAT WASHER 3/8" ZINC	28
8	052-0777	BOLT 3/8"-24 x 3" ZINC	10
9	052-3128	NUT 3/8"-24 UNF ZINC	20
10	052-0775	BOLT 3/8"-24x2-1/2" ZINC	10
11	051-0783	WASHER 3/8" FLAT THICK S/S	8
12	008-0590	LEFT COVER SPRING	2
13	008-0589	RIGHT COVER SPRING	2
14	004A0382	AUTO. MOVEMENT ARM ASSY	2
15	056-0167	KEY 1/4"sq.x1" OVERSIZED	2
16	051-0780	WASHER 3/8" FLAT S/S	4
17	075-1650	FLANGED BEARING W/ GREASE FITING 90°	4
18	052-2071	WASHER 3/8" CONTACT BELLVILLE STL.	8
19	051-0441	BOLT 1/2"-13 x 1 1/2" SS	8
20	051-0790	WASHER 1/2" FLAT SS	8
21	051-0630	NUT 1/2"-13 SS	8



SECTION A-A

MACHINE		680A		SIPROMAC	
PART		TABLE & CENTRAL SHAFT ASSY		ST-GERMAIN DE GRANTHAM	
ITEM		CNC		QUEBEC CANADA	
DATE		04-08-27		N.T.S.	
DWG BY		B.C.		DEPT.	
APP. BY				M	
QTY.		1		004A0239	

A	REDRAWN S.E.	04-08-27	B.C.
LET.	MODIFICATION	DATE	INT.




MACHINE FRONT VIEW

650-680-700 A

CENTRAL SHAFT ASSEMBLY


1005A0392

ITEM	PART #	DESCRIPTION	QT.
1	004A0378	FRONT P.C. BOARD SUPPORT PRE-ASS'Y	1
2	051-0092	SCREW #4-40 x 1 1/4" FLAT SLT S/S	4
3	051-0713	WASHER #4 FLAT S/S	4
4	058-0120	CPVC SPACER 0.120" x 1/4" x 5/8"	4
5	051-0540	NUT #4-40 HEX S/S	8
6	051-0715	WASHER #4 LOCK SS	4



USE JIG TO INSTALL, IN REGARDS TO OPENINGS IN ITEM #1

033-0015 OR 033-0017
KEYBOARD (NOT INCLUDED)




MACHINE		DEPT. TOL. METRIC INCH		USINAGE ±0.1 ±0.004		STIPROMAC	
PART		OLEVING ±0.1 ±0.004		STIPROMAC		ST-GERMAN DE GRANTHAM	
FRONT PC BOARD SUPPORT ASS'Y		SCUDING ±0.1 ±0.004		N.T.S.		QUEBEC CANADA	
ITEM		CNC		DATE 05-08-11		QTY. 1	
MAT.		DWG BY M.A.L.		DATE 05-10-25		005A0392	
APP. BY		DATE		DATE		DATE	

E	REDRAWN/GASKET REMOVED	05-08-11	M.A.
LET.	MODIFICATION	DATE	INT.

1005-0472

ITEM	PART #	DESCRIPTION	QT.
1	004-0176	STRUCTURE PRE-ASSY	1
2	005-0582	REAR MC-40 SUPPORT ASSY	1
3	051-0287	BOLT 1/4-20 x 3-1/4" S/S	4
4	051-0757	WASHER 1/4" FLAT THICK S/S	4
5	058-0140	PLASTIC SPACER 0.266" x 1/2" x 2 1/4"	4
6	051-0750	WASHER 1/4" LOCK S/S	4
7	051-0580	NUT 1/4"-20nc. S/S	4
8	057-5010	NYLON SCREW #10 RECEPTACLE INSERT	8
9	001A3230	STRUCTURE COVER	1
10	054-0180	METAL SCREW #6 x 3/8" PAN SLOT S/S	8



-UNE FOIS L'ITEM 2 INSTALLÉ, UTILISER DE L'ADHÉSIF MARIN 5200 #169-0210 POUR SCELLER -
LE HAUT, LES CÔTÉS ET LES COINS DU BAS ILE CÔTÉ DU DESSOUS (NEST PAS SCELLÉ)

-ONCE ITEM 2 IS INSTALLED, USE 169-0210 5200 MARINE ADHESIVE TO SEAL TOP, SIDES & BOTTOM CORNERS (UNDER SIDE NOT SEALED).


MACHINE	700A & 680A		STRUCTURE ASSY		SIPROMAC	
PART					ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM			N.T.S.			
QTY.	1		M - I		1	
DATE	04-02-17		DATE		0005-0472	
BY	B.C.		BY			
APP.	APP.		APP.			

B	AJOUTER 680A	04-01-22	J.G.
A	REDESSINE ET MODIF. #A-0382	04-02-17	B.C.
LET.	MODIFICATION	DATE	INT.

1005-0617

NOTE:

-USE "BLUE-242" THREAD LOCK #169-0415



ITEM	PART #	DESCRIPTION	QT
1	004-0214	COVER GUARD PRE ASSY	2
2	004-0215	SIDE COVER GUARD PRE-ASSY	2
3	004-0208	COVER GUARD CORNER ASSY	4
5	057-0120	PLASTIC THUMB NUT 1/4-20 "	12
6	051-0580	NUT 1/4"-20nc. S/S	12
7	051-0217	SET SCREW 1/4"-20nc. X 1" S/S	8
8	051-0740	WASHER 1/4" FLAT S/S	20
9	051-0180	BOLT. HEX. 1/4"-20 NC. x 1/2" S/S	16
10	002-0491	COVER GUARD BUMPER	4
11	051-0190	BOLT 1/4-20 x 3/4" HEX S/S	4
12	003-0129	COVER GUARD SWITCH	4
13	051-0086	SCREW 4-40 X 3/4" RND SLOT S/S	8
14	051-0540	NUT #4-40 HEX S/S	8
15	051-0258	SET SCREW 1/4-20 x 2" S/S	4
16	057-0050	NYLON FLAT TIE HOLDER (FTH-9)	24


MACHINE 680A		DEPTH TOL. METRIC INCH USINAGE ± 0.1 ± 0.004 TOLERIE ± 0.5 ± 0.020 SOUDAGE ± 0.5 ± 0.020	SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA
PART COVER GUARD ASSEMBLY		N.T.S.	
ITEM	CNC	DATE	QTY.
1		04-08-02	1
2		04-08-02	
3		04-08-02	
4		04-08-02	
5		04-08-02	
6		04-08-02	
7		04-08-02	
8		04-08-02	
9		04-08-02	
10		04-08-02	
11		04-08-02	
12		04-08-02	
13		04-08-02	
14		04-08-02	
15		04-08-02	
16		04-08-02	

A	REDRAWN S.E.	04-08-02	B.C.
LET.	MODIFICATION	DATE	INT.

005-0617	
----------	--

1005B0547

ITEM	PART #	DESCRIPTION	QT.
1	004A0254	SEAL BAR PRE-ASSY	1
2	051-0256	BOLT 1/4"-20nc X 1 3/4" CAP SKT S/S	5
3	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 600 (2.1)	1
4	051-0581	NUT 1/4"-20 NYLON LOCK S/S	10
5	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	10
6	051-0740	WASHER 1/4" FLAT S/S	8
7	001A1901	EXTERIOR BELLOW'S COVER	1
8	002A0357	SEAL BAR SUPPORT	1
9	001A1900	INTERIOR BELLOW'S COVER	1
10	001-0269	SEAL BAR GUIDE	2



-TWIN SEAL OPTION-

VUE A

700A	4
680A	4
650A	4
MACHINE	QTY

SIPROMAC
ST GERMAIN DE GRANTHAM
QUEBEC CANADA

USEFUL TO METRIC INCH	INCH
TOLEANCE	± 0.007
SOLIDAGE	± 0.020
N.T.S.	

650A, 680A & 700A

SEAL BAR ASSY WISUPPORT

DATE 06-01-16

APP BY

DATE 26-08-28

005B0547



0601-16 M.A.

MODIFICATION

DATE INT.

1004A0254

ITEM	PART #	DESCRIPTION	QT.
1	002A0332	SEAL BAR	1
2	039-0268	DOUBLE SEAM BAND (8MM) (3.1)	1
3	176-0200	TEFLON TAPE 5MIL (0.104)	1
4	056-1401	3/8" SET SCREW BANDING BUCKLE S/S	2
5	052-0393	SCREW 1/4-28x3/16" SKT SET OVAL POINT ZINC	2
6	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	001A2742	8mm ELEMENT BINDER	2
10	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
11	051-0572	LOCK NUT #10-24 S/S	2
12	171-0180	TAPE CLEAR SUPER BOND 3/4" 854.5mm (0.026)	2



-DÉTAIL A-

-TWIN SEAL OPTION-


700A	4
580A	4
650A	4
580A	2
MACHINE	QTY

PART #		580A, 650A, 680A & 700A		MACHINE		SIPROMAC	
DESCRIPTION		SEAL BAR PRE-ASSY		ST-GERMAIN DE GRANTHAM		QUEBEC CANADA	
ITEM		CNC		N.T.S.		M-I	
DATE		06-01-16		NO		LIST	
APP. BY		D		DATE		004A0254	
MODIFICATION		DATE		INT.			
ADDED 052-0393		06-04-19		M.A.			
REDRAWN		06-01-16		M.A.			
LET.							

INSTALLER CONTRE L'ENCOCHE DE L'ITEM #8 (4) INSTALL AGAINST NOTCH OF ITEM #8

1005B0548

ITEM	PART #	DESCRIPTION	QT.
1	004A0255	SEAL BAR PRE-ASSY	1
2	051-0581	NUT 1/4"-20 NYLON LOCK S/S	10
3	051-0256	BOLT 1/4"-20nc. X 1 3/4" CAP SKT S/S	5
4	051-0230	HEX BOLT 1/4-20 x 1 1/4" SS	10
5	051-0740	WASHER 1/4" FLAT S/S	8
6	002A0357	SEAL BAR SUPPORT	1
7	001A1901	EXTERIOR BELLOWS COVER	1
8	001A1900	INTERIOR BELLOWS COVER	1
9	001-0269	SEAL BAR GUIDE	2
10	038-0230	WIRING DUCT W/ ADHESIVE BACKING (0.35" x 0.5" x 600 (2.1)	1



-BAG CUT OPTION-

MACHINE	DEPT. 101	METRIC	INCH
650A, 680A & 700A	USITAGE	± 0.005	± 0.002
SEAL BAR ASSY W/SUPPORT	CHISEL	± 0.1	± 0.005
	SOLDER	± 0.5	± 0.020
		N.T.S.	

700A	4
680A	4
650A	4
MACHINE	QTY

SIPROMAC	
ST-GERMAIN DE GRANVILLE	
QUEBEC CANADA	


F	REDRAWN	06-01-16	M.A.
LET.	MODIFICATION	DATE	INT.

DATE	06-01-16	NO.	101
DATE	06-05-27	NO.	101
DATE	06-05-27	NO.	101
DATE	06-05-27	NO.	101

M-I	101
005B0548	

004A0255

ITEM	PART #	DESCRIPTION	QT.
1	009A0193	ECO SEAL BAR	1
2	077-0095	SPRING C 0360-059-1250 S/S	2
3	001-2666	ELEMENT BINDER	2
4	051-0146	SCREW 10-24 X 1" PAN PHIL S/S	2
5	051-0572	LOCK NUT #10-24 S/S	2
6	051-0100	SCREW 8-32 X 3/8" PAN PHIL S/S	2
7	051-0550	NUT #8-32 SS	4
8	027-0400	CONNECTOR ADAPTOR	2
9	179-0003	SILICONE 2mm x 15mm ADHESIVE (0.89)	1
10	176-0220	TEFLON TAPE, PRESS SENSITIVE 2" 854.5mm (0.104)	1
11	039-0269	SEAL CUT ELEMENT (0.0892)	1
12	056-1400	1/4" SET SCREW BANDING BUCKLE S/S	2
13	176-0203	TEFLON TAPE, 5MIL UNCOATED ZONE 854.5mm (0.085)	1
14	171-0180	TAPE CLEAR SUPER BOND 3/4" 854.5mm (0.026)	2



CUTTING ELEMENT THIS SIDE

-BAG CUT OPTION-

700A	4
680A	4
650A	4
580A	2
MACHINE	QTY

MACHINE	DEPT. 101	METRIC	INCH
580A, 650A, 680A & 700A	101	101	101
PART	TOLERANCE	± 0.5	± 0.020
	SOUDAGE	± 0.5	± 0.020
			N.T.S.
ITEM	CNC	DATE	06-01-16
DESIGNED BY	MAL	DATE	06-05-16
APP. BY			
MAT.			


700A	4
680A	4
650A	4
580A	2
MACHINE	QTY

D	REDESSINE	06-01-16	M.A.
LET.	MODIFICATION	DATE	INT.

M-I	LIST
004A0255	

004B0207

ITEM	PART #	DESCRIPTION	QTY.
1	002B0364	UPPER SEAL BAR SUPPORT	2
2	008-0374	UPPER SEAL BAR RUBBER	2
3	176-0200	TEFLON TAPE (5S) ADHESIVE (2" x 936MM) 0.12	




MACHINE		580A, 650A, 680A & 700A		SIPROMAC	
PART		UPPER SEAL BAR ASSEMBLY		ST-GERMAIN DE GRANTHAM	
ITEM		N.T.S.		QUEBEC CANADA	
DATE		99-08-20		QTY. 2	
BY: S. LAROUCHE		DATE		NO.	
APP.		DATE		NO.	

ADDED 580A	04-11-08	M.A.L.
ADDED 650A WAS 004B0139	00-02-01	S.L.
REDRAWN WAS 004A0207	99-08-20	S.L.
MODIFICATION	DATE	INT.

004B0207

ITEM	PART #	DESCRIPTION	QTY
1	004-0256	SEAL BAR PRE-ASSY (TOP & BOTTOM OPT.)	1
2	002A0357	SEAL BAR SUPPORT	1
3	051-0251	CAP HEX. SKT BOLT 1/4"-20 NC. X 1 1/2" S/S	5
4	001A1901	EXTERIOR BELLOWS COVER	1
5	001A1900	INTERIOR BELLOWS COVER	1
6	001-0269	SEAL BAR GUIDE	2
7	039-0230	WRING DUCT W/ ADHESIVE BACKING (0.35" X 0.5" X 600)	2.07
8	051-0230	HEX. BOLT 1/4"-20 NC. X 1 1/4" S/S	10
9	051-0581	HEX. NUT 1/4"-20 NC. NYLON LOCK S/S	10
10	051-0740	FLAT WASHER 1/4" S/S	8



—VIEW "A-A"—


—OPTION—
TOP & BOTTOM SEALING OR
BI-ACTIVE SEALING OPTION

MACHINE 650A, 680A & 700A		INCH TOLERANCE +0.000 -0.005 N.T.S.		SCALE 1" = 4"	
PART SEAL BAR ASS'Y W/ SUPPORT		METRIC TOLERANCE +0.000 -0.005 N.T.S.		DATE 98-03-11	
ITEM: _____		DATE 98-03-11		NO. 005A0549	
DATE 98-03-11		DATE 98-03-11		NO. 005A0549	
BY J.W.A. PROVENCER		DATE 98-03-11		NO. 005A0549	
APP. _____		DATE 98-03-11		NO. 005A0549	

LET.	MODIFICATION	DATE	INT.
E	MODIF #A-0399	04-04-27	B.C.
D	ADDED 650A WAS 005A0369	00-02-01	S.L.
C	40 BOLTS #051-0230 WAS 24	98-05-14	L.M.
B	REMOVE BOLTS #051-0250/MODIF. #A-0263	98-03-11	A.P.
A	REDRAWN / MODIF. NO. A-0245		

1004-0256

ITEM	#PART	DESCRIPTION	QT.
1	002-0332	SEAL BAR (TABLE)	1
2	009-0029	CONNECTOR	2
3	179-0003	SILICONE 2mm x 15mm ADHESIVE (852mm EA.)	0.890
4	176-0220	TEFLON TAPE (10S) ADHESIVE (862mm EA.)	0.109
5	176-0200	TEFLON TAPE (5S) ADHESIVE (2 x 862mm)	0.218
6	039-0220	BI-ACTIVE SEALING ELEM. (992mm EA.)	0.104
7	052-0395	SET SCREW 1/4"-20 x 5/16" (OVAL POINT)	2
8	052-0250	SCREW #8-32 x 1 1/2" RND SLOT BRASS	2
9	051-0550	NUT #8-32 S/S	4
10	027-0400	CONNECTOR ADAPTOR	2
11	001-0266	TEFLON HOLD DOWN PLATE	2
12	051-0147	HEX. BOLT #10-24 x 1" S.S.	6
13	051-0571	HEX. NUT #10-24 S.S.	6



-TOP AND BOTTOM SEALING OPTION-


MACHINE		TOLERANCE		NCH	
580A, 650A, 680A & 700A		USINAGE		± 0.1	
PART		TOLERANCE		± 0.004	
SEAL BAR ASSEMBLY		SOUDAGE		± 0.5	
ITEM:		CNC:		N.T.S.	
DATE		DATE		DATE	
95-12-29		95-12-29		95-12-29	
M.L.		M.L.		M.L.	
APP.		APP.		APP.	
M-I		M-I		M-I	
4		4		4	
004-0256		004-0256		004-0256	

D	ADDED 580A	04-11-29	M.A.L.
C	MODIFICATION #A-039B (CONNECTEUR)	04-04-19	J.G.
B	RE-DRAWN	95-12-29	M.L.
LET.	MODIFICATION	DATE	INT.

005A0437

ITEM	#PART	DESCRIPTION	QT.
1	002A0378	UPPER SEAL BAR SUPPORT	1
2	051-0220	SCREW 1/4"-20 NC. X 1" CAP HEX. SKT S/S	8
3	002A0396	UPPER SEAL BAR	1
4	009-0029	TOP & BOTTOM SEAL CONNECTOR WELDED	2
5	052-0250	SCREW #8-32 NC. X 1 1/2" RND SLOT BRASS	2
6	051-0550	HEX. NUT #8-32 NC. S/S	4
7	027-0400	CONNECTOR ADAPTOR	2
8	179-0003	SILICONE 2mm x 15mm ADHESIVE (852mm EA.)	0.890
9	176-0200	TEFLON TAPE (5S) ADHESIVE (862mm EA.)	0.109
10	176-0220	TEFLON TAPE (10S) ADHESIVE (2x862mm)	0.218
11	039-0220	BI-ACTIVE SEALING ELEM. (992mm EA.)	0.104
12	052-0395	SET SCREW 1/4"-20 NC. X 5/16" (OVAL POINT)	2
13	001A1571	UPPER TEFLON HOLDER	2
14	051-0121	SCREW #8-32 NC. X 1" FLAT PHILL. S/S	9
15	051-0550	HEX. NUT #8-32 NC. S/S	9


NOTE: CUT OFF HEAD OF SCREW AFTER ASSEMBLING



THIS SIDE OF SEAL BAR TO FIT FLUSH W/ SUPPORT

VIEW "C-C"
(END VIEW ASSEMBLY)

TOP & BOTTOM SEALING OPTION




DETAIL "B"

G	ADDED 580A	04-12-15	M.A.L.
F	MODIFICATION #A-0398 (CONNECTEUR)	04-04-19	J.G.
E	ADDED 650A WAS 005A0404	00-02-01	S.L.
D	REDRAWN/ WAS ALSO 004-0258	98-04-20	A.P.
LET.	MODIFICATION	DATE	INT.

MACHINE 580A, 650A, 680A & 700A		SIPROMAC	
PART UPPER SEAL BAR ASS'Y W/SUPPORT		ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
ITEM:	QTY:	DATE 98-04-20	NO. 005A0437
DATE:	BY:	DATE 04-12-16	QTY 2

ITEM	PART #	DESCRIPTION	QT.
1	106-0050	VALVE 2WAY 24V 1-1/4"NPT(B60)60Hz	2
2	103-0247	CLOSE NIPPLE 1 1/4" NPT ZINC	2
3	103-0587	RED. BUSH. 2"npt. X 1 1/4"npt ZINC	2
4	004A1621	VAC./ATM. VALVE SUPP. PRE-ASSY	2
5	103-0260	CLOSE NIPPLE 2"NPT ZINC	4
6	106-0060	VALVE 2WAY / 24V / 60Hz / 2" NPT	2
7	103-0487	T 2" NPT GALV.	1
8	103-0760	STRAIGHT 2"mnpt. X 2" HOSE ZINC	3




NOTE:



-UTILISER RUBAN DE TEFLON #154-0060 & TEFLON LIQUIDE #154-0030 POUR L'ASSEMBLAGE.

MACHINE		650A, 680A & 700A		DEPT. TOL. METRIC INCH FARGES ± 0.004 TOIGRE ± 0.5 SOLDAGE ± 0.5 ± 0.027		SIPROMAC ST-GERMAIN DE GRANTHAM QUEBEC CANADA	
PART		VACUUM / ATMOSPHERE VALVE ASSY		N.T.S.			
ITEM	CNC	DATE	04-03-03	DEPT.	M-I	QTY.	1
MAT.		DATE	25-11-94	NO	004-0505		

H	REMOVED SORT AIR OPTION NOTE	05-10-31	M.A.
G	004A1621 WAS 004-0183	06-09-27	M.A.
F	REMOVED 2 ITEMS 103-0092	05-09-21	M.A.
E	REDESSINE ET AJOUT OPTION	04-03-03	B.C.
LET.	MODIFICATION	DATE	INT.




ELECTRICAL DRAWING



Tested with: V 3 Ph Hz

<i>name</i>	<i>plate</i>
-------------	--------------

measured



category	VACUUM PACK	model	680A	volt	3 Ph / 50 Hz					SIPROMAC			
system	POWER			circuit	year	month	day	block	St-Germain de Grantham QUEBEC, CANADA				
usual					05	01	18						
functions					concept	draw	app						
options					pp	pp	DL		006-1610		PAGE	1 de 1	

Tested with: V 3 Ph Hz

L1

L2



L3

G

name

plate

measured



category	VACUUM PACK		680A		1 Ph / 50 Hz		006-1600		PAGE 1 de 1	
	POWER		circuit		year month day		concept draw app		PP PP PP DL	
	usual		05 01 18		05 01 18		006-1600		PAGE 1 de 1	
	functions		options		options		options		options	

SIPROMAC
St-Germain de Grantham
QUEBEC, CANADA


Tested with: V 3 Ph Hz

name
plate

measured

VACUUM PUMP

Pump
Model :
Sn :
Motor
Model :
Sn :
Vac :
Vacuum : mb



OL31
(12blk)

C31

(12 blk)

F 31

WEL

Bottom Left
Sealing Bar

Bottom Right
Sealing Bar

Top Sealing
Bar (Option)

C33

F 33

TR2

C34


C35

C36

WTB

Category	VACUUM PACK	model	680A	volt.	3Ph 60Hz	year	month	day	block
system	POWER			circuit		05	01	18	
usual functions						concept	draw	app	DL
options						PP	PP	PP	DL
					006-1630				
					PAGE 1 de 1				
					SIPROMAC				
					St-Germain de Grantham				
					QUEBEC, CANADA				


Gnd	L1	L2	L3
-----	----	----	----



Pump	:
Model	:
Sn	:
Motor	:
Model	:
Sn	:
Vac	:
Vacuum	:

<i>name</i>	<i>plate</i>
-------------	--------------

measured




category	VACUUM PACK		model	680A		volt		1Ph 60Hz				SIPROMAC			
system	POWER					circuit		year	month	day	block	St-Germain de Grantham QUEBEC ,CANADA			
usual								05	01	18		concept	draw	app	
options								pp	pp	pp	DL	006-1620 PAGE 1 de 1			



RC filters must be connected on each coil AC (not shown on diagram)

category	VACUUM PACK		model	680A		vol		ALL				SIPROMAC				
system	CONTROL SUPPLY				circuit	control		year	month	day	block	St-Germain de Grantham QUEBEC, CANADA				
usual							05	03	03							
fonctions							concept	draw	app							
options							pp	pp	DL							
											006-1637				PAGE 1 de 8	



SIPROMAC
St-Germain de Grantham
QUEBEC, CANADA

VACUUM PACK model **680A** volt **ALL**

SECURITY

year **05** month **03** day **03** block

concept **PP** draw **PP** app **DL**


006-1637 PAGE 2 de 8

- The left or right sides are based on operator position facing the control panel


- RC filters must be connected on each coil AC (not shown on diagram)




category	VACUUM PACK	model	680A	voit				ALL				SIPROMAC St-Germain de Grantham QUEBEC, CANADA			
system	POWER COMMAND			circuit				year	month	day	block				
usual								05	03	03					
functions							concept	draw	app						
options							pp	pp	DL			006-1637 PAGE 3 de 8			




category	VACUUM PACK	model	680A	vol.				ALL				SIPROMAC			
system	VACUUM AND ATMOSPHERE			circuit				year	month	day	block	St-Germain de Grantham QUEBEC ,CANADA			
usual								05	03	03					
functions								concept	draw	app					
options								pp	pp	DL		006-1637			
												PAGE 4 de 8			



category	VACUUM PACK		model	680A		ALL				SIPROMAC			
system	BELLOWS			circuit	year	month	day	block	St-Germain de Grantham QUEBEC, CANADA				
usual					05	03	03	5					
fonctions				concept	draw	app	006-1637				PAGE	5 de 8	
options				PP	PP	DL							





- The left or right sides are based on operator position facing the control panel
- RC filters must be connected on each coil AC (not shown on diagram)




category		VACUUM PACK		model		680A		vol.		ALL				SIPROMAC											
system				COVER MOVEMENT				circuit				year		month		day		block		6		St-Germain de Grantham		QUEBEC, CANADA	
usual												05		03		03									
functions												concept		draw		app		DL		006-1637		PAGE		6 de 8	
options												PP		PP		DL									

SIPROMAC
St-Germain de Grantham
QUEBEC, CANADA







Category		model	680 A	vol.	SIPROMAC			
system		SÉCURITÉ BRAS ET COUVERCLE		circuit		St-Germain de Grantham		
usual						QUEBEC, CANADA		
functions								
options								
		year	month	day	block	app	DL	
		05	03	03		PP	PP	
		concept	draw					
		PP	PP					
						006-1637		
						PAGE 8 de 8		



PNEUMATIC DRAWING




ITEM	PART #	DESCRIPTION	QTY.
1	114-0430	AIR FILTER 1/4"NPT	1
2	114-0200	AIR OILER 1/4"NPT	1
3	114-0150	PRESSURE REGULATOR 0-125PSI 1/4"NPT	2
4	114-0250	PRESSURE GAUGE 0-160PSI 1/8"NPT	2
5	114-0820	SOLENOID VALVE 4WAY 1/8"NPT W/FLOW CONTROL	2
6	114-0105	AIR CYLINDER	1
7	106-0070	BELLOWS VALVE	1
8	106-0080	VACUUM VALVE	2
9	106-0050	ATMOSPHERE VALVE	2

(NOTE: DO NOT REFER TO THIS LIST FOR ASSEMBLY)

-E-BOX-

-UNDER TABLE REAR VIEW SCHEMATIC-



-NOTE:
-FOR VALVE INSTALLATION
ON E-BOX SEE DRAWING
007-0041

650A AUTOMATIC
PNEUMATIC

SIPROMAC
ST-GERMAIN DE GRANTHAM
QUÉBEC CANADA

ITEM:	DATE:	SCALE:	QTY:
114-0430	97-03-11	1/4"	1
114-0200	DATE	DATE	DATE
114-0150	DATE	DATE	DATE
114-0250	DATE	DATE	DATE

007-0037

RE-DRAWN
LET.


DATE

INT.


DATE

INT.


ITEM	PART #	DESCRIPTION	QTY.
1	114-0860	2 END PLATES KIT 1/4"NPT	1
2	051-0146	SCREW #10-24 x 1" PAN PHIL S/S	3
3	051-0571	NUT #10-24 S/S	3
4	114-0820	VALVE 4 WAY 24VAC 1/8"NPT W/FLOW CONT.	2
5	114-0850	DIN CONNECTOR	2
6	114-1055	ADJEXFLOW CONTROL 1/4"NPT MUFFLER BR.	1
7	101-0058	ELBOW 1/4"NPT x 3/8" T.P. COMP. BR.	5
8	102-0380	MALE CONN. 1/8"NPT x 3/8" T.P. QUICK	2
9	101-1020	HEX PLUG 1/8"NPT BR.	2
10	001-1839	AIR VALVE SUPPORT	1
11	051-0190	BOLT 1/4"-20 x 3/4" S/S	11
12	051-0740	WASHER 1/4" FLAT S/S	1
13	001-1840	VALVE MTD. BRACKET	1
14	101-0315	HEXAGONE NIPPLE 1/4"NPT BR.	4
15	101-1030	HEX PLUG 1/4"NPT BRASS	3
16	005-0524	PNEUMATIC SUPPORT ASSY	2
17	114-0200	LUBRICATOR 1/4"NPT	1
18	101-0200	STRAIGHT 1/4"NPT x 1/4" HOSE BARB BR.	1
19	114-0430	AIR FILTER 1/4"NPT	1
20	114-0147	PRESSURE REGULATOR 0-60PSI 1/4"NPT	1
21	114-0245	PRESSURE GAUGE 0-60PSI 1/8"NPT	1
22	114-0150	PRESSURE REGULATOR 0-125PSI 1/4"NPT	1
23	114-0250	PRESSURE GAUGE 0-160PSI 1/8"NPT	1
24	104-0060	POLYETHYLENE TUBING 3/8" OD LPDE	—
25	104-0077	POLYURETHANE TUBING 3/8" OD SAC BLUE	—




MACHINE		650A AUTOMATIC		SIPROMAC	
PART		E-BOX VALVE INSTALLATION		ST-CERMAN DE GRANTHAM QUEBEC CANADA	
ITEM:	QTY:	N.T.S.	SCALE:	QTY:	1
MAT:	DATE:	DATE:	DATE:	DATE:	DATE:
M. LAVIGNE			007-0041		



— FRONT VIEW —
GAS INJECTION BAR INSTALLATION




DETAIL A



— UNDER TABLE VIEW —
VALVE INSTALLATION

— OPTION GAS INJECTION —

VALVE INSTALLATION		SEE NOTE		TO GAS INJECTION TUBES UNDER TABLE, REMOVE THE FOUR EXISTING CAPS & CONNECT HOSES A,B,C & D		MACHINE 650A AUTOMATIC PART GAS INJECTION KIT INSTALLATION		METRIC TUBES 1/2" M.T. 1/2" O.D. 1/2" I.D. 1/2" L. 1/2" W. 1/2" H. 1/2" T. 1/2" B. 1/2" F. 1/2" S. 1/2" C. 1/2" D. 1/2" E. 1/2" G. 1/2" I. 1/2" J. 1/2" K. 1/2" L. 1/2" M. 1/2" N. 1/2" O. 1/2" P. 1/2" Q. 1/2" R. 1/2" S. 1/2" T. 1/2" U. 1/2" V. 1/2" W. 1/2" X. 1/2" Y. 1/2" Z. 1/2" AA. 1/2" AB. 1/2" AC. 1/2" AD. 1/2" AE. 1/2" AF. 1/2" AG. 1/2" AH. 1/2" AI. 1/2" AJ. 1/2" AK. 1/2" AL. 1/2" AM. 1/2" AN. 1/2" AO. 1/2" AP. 1/2" AQ. 1/2" AR. 1/2" AS. 1/2" AT. 1/2" AU. 1/2" AV. 1/2" AW. 1/2" AX. 1/2" AY. 1/2" AZ. 1/2" BA. 1/2" BB. 1/2" BC. 1/2" BD. 1/2" BE. 1/2" BF. 1/2" BG. 1/2" BH. 1/2" BI. 1/2" BJ. 1/2" BK. 1/2" BL. 1/2" BM. 1/2" BN. 1/2" BO. 1/2" BP. 1/2" BQ. 1/2" BR. 1/2" BS. 1/2" BT. 1/2" BU. 1/2" BV. 1/2" BW. 1/2" BX. 1/2" BY. 1/2" BZ. 1/2" CA. 1/2" CB. 1/2" CC. 1/2" CD. 1/2" CE. 1/2" CF. 1/2" CG. 1/2" CH. 1/2" CI. 1/2" CJ. 1/2" CK. 1/2" CL. 1/2" CM. 1/2" CN. 1/2" CO. 1/2" CP. 1/2" CQ. 1/2" CR. 1/2" CS. 1/2" CT. 1/2" CU. 1/2" CV. 1/2" CW. 1/2" CX. 1/2" CY. 1/2" CZ. 1/2" DA. 1/2" DB. 1/2" DC. 1/2" DD. 1/2" DE. 1/2" DF. 1/2" DG. 1/2" DH. 1/2" DI. 1/2" DJ. 1/2" DK. 1/2" DL. 1/2" DM. 1/2" DN. 1/2" DO. 1/2" DP. 1/2" DQ. 1/2" DR. 1/2" DS. 1/2" DT. 1/2" DU. 1/2" DV. 1/2" DW. 1/2" DX. 1/2" DY. 1/2" DZ. 1/2" EA. 1/2" EB. 1/2" EC. 1/2" ED. 1/2" EE. 1/2" EF. 1/2" EG. 1/2" EH. 1/2" EI. 1/2" EJ. 1/2" EK. 1/2" EL. 1/2" EM. 1/2" EN. 1/2" EO. 1/2" EP. 1/2" EQ. 1/2" ER. 1/2" ES. 1/2" ET. 1/2" EU. 1/2" EV. 1/2" EW. 1/2" EX. 1/2" EY. 1/2" EZ. 1/2" FA. 1/2" FB. 1/2" FC. 1/2" FD. 1/2" FE. 1/2" FF. 1/2" FG. 1/2" FH. 1/2" FI. 1/2" FJ. 1/2" FK. 1/2" FL. 1/2" FM. 1/2" FN. 1/2" FO. 1/2" FP. 1/2" FQ. 1/2" FR. 1/2" FS. 1/2" FT. 1/2" FU. 1/2" FV. 1/2" FW. 1/2" FX. 1/2" FY. 1/2" FZ. 1/2" GA. 1/2" GB. 1/2" GC. 1/2" GD. 1/2" GE. 1/2" GF. 1/2" GG. 1/2" GH. 1/2" GI. 1/2" GJ. 1/2" GK. 1/2" GL. 1/2" GM. 1/2" GN. 1/2" GO. 1/2" GP. 1/2" GQ. 1/2" GR. 1/2" GS. 1/2" GT. 1/2" GU. 1/2" GV. 1/2" GW. 1/2" GX. 1/2" GY. 1/2" GZ. 1/2" HA. 1/2" HB. 1/2" HC. 1/2" HD. 1/2" HE. 1/2" HF. 1/2" HG. 1/2" HH. 1/2" HI. 1/2" HJ. 1/2" HK. 1/2" HL. 1/2" HM. 1/2" HN. 1/2" HO. 1/2" HP. 1/2" HQ. 1/2" HR. 1/2" HS. 1/2" HT. 1/2" HU. 1/2" HV. 1/2" HW. 1/2" HX. 1/2" HY. 1/2" HZ. 1/2" IA. 1/2" IB. 1/2" IC. 1/2" ID. 1/2" IE. 1/2" IF. 1/2" IG. 1/2" IH. 1/2" II. 1/2" IJ. 1/2" IK. 1/2" IL. 1/2" IM. 1/2" IN. 1/2" IO. 1/2" IP. 1/2" IQ. 1/2" IR. 1/2" IS. 1/2" IT. 1/2" IU. 1/2" IV. 1/2" IW. 1/2" IX. 1/2" IY. 1/2" IZ. 1/2" JA. 1/2" JB. 1/2" JC. 1/2" JD. 1/2" JE. 1/2" JF. 1/2" JG. 1/2" JH. 1/2" JI. 1/2" JJ. 1/2" JK. 1/2" JL. 1/2" JM. 1/2" JN. 1/2" JO. 1/2" JP. 1/2" JQ. 1/2" JR. 1/2" JS. 1/2" JT. 1/2" JU. 1/2" JV. 1/2" JW. 1/2" JX. 1/2" JY. 1/2" JZ. 1/2" KA. 1/2" KB. 1/2" KC. 1/2" KD. 1/2" KE. 1/2" KF. 1/2" KG. 1/2" KH. 1/2" KI. 1/2" KJ. 1/2" KK. 1/2" KL. 1/2" KM. 1/2" KN. 1/2" KO. 1/2" KP. 1/2" KQ. 1/2" KR. 1/2" KS. 1/2" KT. 1/2" KU. 1/2" KV. 1/2" KW. 1/2" KX. 1/2" KY. 1/2" KZ. 1/2" LA. 1/2" LB. 1/2" LC. 1/2" LD. 1/2" LE. 1/2" LF. 1/2" LG. 1/2" LH. 1/2" LI. 1/2" LJ. 1/2" LK. 1/2" LL. 1/2" LM. 1/2" LN. 1/2" LO. 1/2" LP. 1/2" LQ. 1/2" LR. 1/2" LS. 1/2" LT. 1/2" LU. 1/2" LV. 1/2" LW. 1/2" LX. 1/2" LY. 1/2" LZ. 1/2" MA. 1/2" MB. 1/2" MC. 1/2" MD. 1/2" ME. 1/2" MF. 1/2" MG. 1/2" MH. 1/2" MI. 1/2" MJ. 1/2" MK. 1/2" ML. 	
--------------------	--	----------	--	---	--	---	--	---	--



MANUEL D'UTILISATEUR

MICROPROCESSEUR MC-40

AVEC OU SANS DÉTECTEUR DE VIDE

EMBALLEUSE SOUS VIDE

TABLE DES MATIÈRES

I INSTRUCTIONS POUR LES OPÉRATIONS

II MÉCANIQUE

- A- Vue de face
- B- Vue de l'arrière
- C- Procédure d'ajustement du couvert
- D- Schéma de l'assemblage de l'axe central
- E- Barres de scellage
(Double scellage)
- F- Dessin des barres de scellage
(Option du coupe sac électrique)
- G- Dessins des barres d'assemblage
(Scellage du haut et du bas en option)
- H- Gas injection kit installation drawing
(gaz injection option)

III ELECTRIQUE

- A- Schéma électrique (Bas voltage)
- B- Schéma électrique (Haut voltage à une phase)
- C- Schéma électrique (Haut voltage à 3 phases)
- D- Schéma électrique (Haut voltage 1 phase 50 Hz)
- E- Schéma électrique (Haut voltage 3 phase 50 Hz)

IV PNEUMATIQUE

- A- Schéma Pneumatique

EMBALLEUSES SOUS VIDE INSTRUCTIONS D'OPÉRATIONS

TABLE DES MATIÈRES

1. Mise en marche de la machine
2. Connexion Électrique
3. Opération
 - 3.1 Principes de travail
 - 3.2 Emballage Spécial
 - 3.2.1 Injection de Gaz
 - 3.2.2 Scellage haut et bas
(bi-active sealing)
 - 3.2.3 Coupe sac électrique
 - 3.3 Ajustement des contrôles digital
 - 3.4 Nettoyage Quotidien
4. Trouble de lancement
 - 4.1 Échec durant le cycle d'emballage
 - 4.2 Vide insuffisant
 - 4.2.1 Fuites dans le sac
 - 4.2.2 Pas de fuite dans le sac
 - 4.2.3 Vide insuffisant dans la chambre
 - 4.3 Scellage Inadéquat
 - 4.3.1 Scellage insuffisant
 - 4.3.2 Pas de scellage
 - 4.3.3 Courant ininterrompu sur les barres de scellage
 - 4.3.4 Le scellage ne tient pas
 - 4.4 Problème avec les valves
 - 4.5 Problème du panneau de contrôle
5. Maintenance Régulière

SIPROMAC INC.

EMBALLEUSES SOUS VIDE

1. MISE EN PLACE DE LA MACHINE:

Avant de choisir le site d'installation de votre machine, veuillez considérer que vous aurez besoin d'espace pour les produits emballés et non-emballés à part de l'espace occupé par la machine elle-même.

Bien vouloir vous rappelez que vous aurez besoin d'un sol bien au niveau pour votre installation. Spécialement avec les modèles mobiles, le poids de la pompe peut gauchir la machine et le couvercle ne fermera plus correctement.

Avant de commencer à travailler, vérifier l'huile de la pompe pour voir si elle est en quantité suffisante. Bien vouloir ne jamais utiliser une huile autre que celle recommandée par le fabricant. Ne pas excéder la quantité indiquée quand vous ajoutez ou faites le changement d'huile et faites votre vérification hebdomadairement.

En raison de la viscosité de l'huile, la machine sera plus difficile à démarrer à basses températures. Ainsi donc la pompe doit être placée dans un endroit où la température est d'au moins 50°F (+10°C). D'autre part, l'air doit circuler librement aux alentours de la pompe pour permettre le refroidissement dans les cas où la température des opérations atteindrait 160°F (70°C) ou la température maximale permise.

2. CONNECTION ÉLECTRIQUE:

Les connections électriques doivent se faire par du personnel qualifié. La personne désignée doit s'assurer que les entrées électriques correspondent au voltage et à l'ampérage approprié de la machine.

Un schéma électrique accompagne chacune de nos machines.

Une étape importante dans le branchement de la machine est de s'assurer que le moteur de la pompe tourne dans une rotation appropriée.

Attention: Le moteur de la pompe ne devrait pas tourner plus de 3 ou 4 secondes dans une mauvaise rotation car il en résultera des dommages sérieux. La rotation est indiquée par une flèche sur le moteur de la pompe.


3. OPÉRATION:

3.1 Principes de travail:

Un emballage sous vide est un cycle composé de 3 étapes. Premièrement le vide est fait et l'air est complètement enlevé de la chambre et du sac contenant le produit. (Voir figure 1). Ensuite c'est possible d'injecter du gaz neutre par les conduits si le produit est très délicat. Finalement, un mécanisme pousse la barre de scellage sur le support de caoutchouc pour sceller le sac

Pour obtenir de beaux emballages, les produits et les sacs doivent être de taille proportionnelles. L'ouverture du sac ne devrait jamais excéder 2" (50cm) au delà des barres de scellage. Le produit doit être centré en hauteur par rapport aux barres de scellage en ajustant les écarteurs qui vous sont fournis.

Pour obtenir un bon scellage, assurez-vous qu'il n'y a pas de résidu de graisse qui reste entre les côtés intérieurs des sacs où le scellage doit être fait.



3.2 Empaquetage Spécial:

3.2.1 Injection de Gaz (option):

Il y a une pression atmosphérique de 14 lbs / pouce carré (= 1 kg / cm carré) sur les produits quand le vide demandé est atteint. Les produits qui peuvent être endommagés par une haute pression doivent être emballés avec un vide partiel et la pression doit être contrebalancée en injectant du gaz dans le sac (nitrogène ou dioxyde de carbone) avant le scellement et après avoir atteint le vide.

Pour l'injection de gaz, les sacs sont placés sur les barres de scellage, l'ouverture placée au dessus des conduits de gaz qui sont montés le long des barres de scellage. Après que le vide soit atteint, la valve du vide se ferme et la valve du gaz s'ouvre. Le pourcentage de gaz peut être ajusté par le menu du programme.

Le réservoir de gaz et la valve de pression qui est rattachée au réservoir ne sont pas fournis par Sipromac. La pression pour le régulateur de gaz devrait être ajustée approximativement à 5 lbs/pouce carré (1/3 Kg/cm carré). Chaque machine a un adaptateur pour la connexion de gaz quand l'option de l'injection de gaz est commandée.

3.2.2 Scellage Haut et Bas (optionnel):

Pour le scellage des sacs en aluminium comme pour le café il est impératif d'avoir une barre de scellage en haut et en bas.

3.2.3 Coupe sac électrique: (optionnel):

Cette option est utilisée pour obtenir un paquet dont l'excédent de film au niveau du scellage doit être coupée très près de la ligne de scellage. (cette option ne peut pas être utilisée avec le scellage Haut et Bas)

3.3 Les opérations de l'emballage sous vide:

Note: Reportez-vous aux menus structure de la page 8 et aux détails du panneau de contrôle sur la page 9

3.3.1 Bases:

Utilisez la touche "POWER" pour initier le bouton ON/OFF sur votre machine sous vide. Quand votre unité sera en fonction le dernier programme exécuté apparaîtra sur l'écran à cristaux liquides.

Utilisez la touche "ESC" pour passer du menu programme au menu fonctions et du menu des fonctions au menu des programmes.

Dans le menu des fonctions, utilisez la touche "SELECT" pour sélectionner une fonction et la touche "ENTER" pour exécuter la sélection.

Dans le menu des programmes, utilisez la touche "SELECT" pour sélectionner un programme et la touche "Enter" pour accéder ou modifier la sélection.

Dans les programmes du sous menu, utilisez la touche "ENTER" pour voir défiler les paramètres et lorsque ces derniers clignotent pour indiquer ils sont dans le mode d'acquisition. Quand la séquence de tous les paramètres se sont affichés, on revient automatiquement au début de la liste.

Dans les programmes du sous menu, utilisez la touche "ESC" pour revenir au menu des programmes. Pressez n'importe quelle touche pour effacer les messages d'erreur qui peuvent s'afficher sur l'écran à cristaux liquide.

3.3.2 Menu des fonctions:

3.3.2.1 Créer un programme:

Quand vous exécutez la fonction "create a program", le programme sous menu est atteint en commençant par l'identification. L'identification initiale "PxxNO NAME" est donné au programme et tous les paramètres sont établis à zéro; le numéro du programme est alloué automatiquement.

3.3.2.2 Supprimer un programme:

En exécutant la fonction de "delete a program", vous avez accès au menu des programmes et le numéro du premier programme en mémoire clignote pour indiquer le mode de suppression. Utilisez la touche "SELECT" pour sélectionner un programme et la touche "ENTER" pour avoir accès et confirmer la suppression de la sélection. Utilisez la touche "ESC" pour annuler une suppression et quitter la fonction. Quand vous quittez la fonction, le nombre des programmes actuels sur l'écran à cristaux liquides cesse de clignoter.

3.3.2.3 Choisir le mode d'opération:

Quand vous exécutez la fonction "Select Operating Mode", laquelle est disponible seulement pour les unités automatiques, la sélection en cours clignote pour vous indiquez le mode. Utilisez la touche "SELECT" pour parcourir les modes d'opération, lesquels sont automatiques, semi-automatiques et manuels.

Le mode d'opération sera validé et exécuté automatiquement. Utilisez la touche "ESC" ou "ENTER" pour quitter la fonction et retourner au menu des programmes.

3.3.3 Menu des Programmes:

3.3.3.1 Identification des Programmes:

Pour un programme sélectionné, choisissez l'identification en utilisant le panneau de contrôle numérique avec la chartre des caractères et pressez sur la touche numérique jusqu'à ce que le caractère soit sélectionné (4 x pour la valeur numérique). Utilisez la touche "ENTER" pour valider le caractère ainsi que la chaîne de caractères jusqu'à la fin (la nouvelle chaîne de caractères clignote). Vous pouvez utiliser la touche "ESC" pour revenir en arrière dans le cas où vous vous êtes trompé et que vous voulez effacer le caractère.

Exemple: EXAMPLE 1 → (9 caractères)

Touche 2, 2, ENTER	→ E
Touche 8, 8, 8, ENTER	→ X
Touche 1, ENTER	→ A
Touche 5, ENTER	→ M
Touche 6, ENTER	→ P
Touche 4, 4, 4, ENTER	→ L
Touche 2, 2, ENTER	→ E
Touche 9, 9, 9, ENTER	→ espace
Touche 1, 1, 1, 1, ENTER	→ 1

Touche ENTER pour valider la chaîne de caractères

3.3.3.2 L'ajustement du niveau de Vide (capteur de vide désactivé):

Pour un programme sélectionné, ajustez le niveau de vide, en secondes; la validation est automatiquement exécutée après la deuxième entrée digitale (Le nouveau temps de vide clignote). En cours de traitement, utilisez la touche "ENTER" pour valider la valeur du niveau de vide et la touche "ESC" pour revenir en arrière et changer la valeur du niveau de vide (La valeur du niveau de vide la plus ancienne clignotera à ce moment).

Exemples: 1 sec. → Touches 0, 1 ou 1, ENTER
15 sec. → Touches 1, 5

3.3.3.3 L'ajustement du niveau de Vide (capteur de vide en activé):

Pour un programme sélectionné, ajustez le niveau de vide avec les valeurs; le point décimal est automatiquement inséré suivant la deuxième entrée digitale et la validation est automatiquement exécutée après la troisième entrée digitale (La nouvelle valeur du niveau du vide clignote). Le niveau de vide est arrondi à la demie la plus près de la valeur. En cours de traitement, utilisez la touche "ENTER" pour valider la valeur du niveau de vide et la touche "ESC" pour revenir en arrière et changer la valeur du niveau de vide (La valeur du niveau de vide la plus ancienne clignotera à ce moment). Ajustez le niveau du vide à zéro pour pouvoir contourner le capteur de vide et procédez en réglant seulement le " Temps de vide Plus" (Vacuum plus time).

Exemples: 90.0% ➔ Touches 9, 0, 0 ou 9, 0, ENTER ou
Touches 9, 0, 1 ou 9, 0, 2 or 9, 0, 3 ou 9, 0, 4
97.5% ➔ Touches 9, 7, 5 ou
Touches 9, 7, 6 ou 9, 0, 7 or 9, 0, 8 ou 9, 0, 9
0.0% ➔ Touches 0, 0, 0 ou 0, ENTER

3.3.3.4 Ajustement du Temps de Vide "Plus" (capteur de vide activé):

Pour un programme sélectionné, réglez le “temps de vide plus” en secondes; la validation est automatiquement exécutée après la deuxième entrée digitale (La nouvelle valeur du “temps de vide plus” clignotera à ce moment). En cours de traitement, utilisez la touche “ENTER” pour valider la nouvelle valeur du “temps de vide plus” et la touche “ESC” pour revenir et recommencer avec de nouvelles valeurs (la valeur la plus ancienne du “temps de vacuum plus” clignotera).

Exemples: 1s → Touche 0, 1 or 1, ENTER
15s → Touche 1, 5

3.3.3.5 Ajustement de l'injection de gaz (capteur de vide désactivé):

Pour sélectionner un programme placer le niveau d'injection de gaz en suivant la même procédure que pour le niveau de vide. Gardez en mémoire que plus le temps d'injection de gaz est haut, moins la pression du sellage sera forte. Un certain niveau de vide doit être maintenu pour un bon fonctionnement.

3.3.3.6 Ajustement de l'injection de gaz (capteur de vide activé):

Pour sélectionner un programme placer le niveau d'injection de gaz en suivant la même procédure que pour le niveau de vide; L'ajustement pour le gaz le plus haut devrait être de 10% au-dessous du niveau de l'ajustement de vide.

3.3.3.7 Ajustement du cachetage:

Pour sélectionner un programme le temps de cachetage, en commençant par les secondes; le point décimale est automatiquement insérée après la première entrée de chiffre et la validation est automatiquement effectuée après la troisième entrée de chiffre (le nouveau temps de cachetage clignote). Le temps de cachetage est arrondi à la moitié la plus proche du cent. À un milieu l'entrée des données, utiliser la clé "ENTER" pour valider l'heure du cachetage et la clé "ESC" pour revenir en arrière et reprogrammer le temps cachetage avec de nouvelles données (le vieux temps de cachetage clignote).

Examples:

- 4.50s → clés 4, 5, 0 or 4, 5, ENTER or
clés 4, 5, 1 or 4, 5, 2 or 4, 5, 3 or 4, 5, 4
- 2.35s → clés 2, 3, 5 or
clés 2, 3, 6 or 2, 3, 7 or 2, 3, 8 or 2, 3, 9
- 0.00s → clés 0, 0, 0 or 0, ENTER

3.3.4 Exécution de cycle de vide :

Pour les unités manuels ainsi que les unités automatiques faire la mise en marche manuelle, fermer le couvercle afin de lancer un cycle de vide. Pour l'unité automatique faire mise en marche semi-automatique ou automatique, utilisez le bouton "ARRÊT / DÉBUT" pour lancer ou interrompre un cycle de vide. Le programme sélectionné peut être lancé seulement dans le programme du menu, au moment où aucune modification n'est nécessaire, et l'accès des autres programmes et des fonctions ne sont pas requis. Pendant l'exécution du cycle le statut d'opération est séquentiellement affiché sur l'écran à cristaux liquides, excepté pour les paramètres établis à zéro, qui ne sont pas montrés:


- niveau de vide de la chambre pendant la séquence,
- vide additionné du temps pendant le vide plus la séquence,
- niveau de vide de la chambre pendant la séquence d'injection de gaz,
- statut de temps de cachetage pendant la séquence de cachetage,
- niveau de vide de la chambre pendant La séquence d'atmosphère .7

Pendant l'exécution du cycle, utilisé la clef "1" pour interrompre la séquence de vide et pour exécuter la séquence suivante, soit l'injection du gaz ou le cachetage, suivi de la clé "ENTER" afin d'accéder et modifier le programme; les paramètres deviennent valides seulement pour les cycles suivants de vide.


3.3.5 System monitor:

Pour accéder le menu des diagnostics, monter la puissance de la machine d'emballage sous vide tout en maintenant le bouton "ESC" enfoncé. Utilisez la clé "SELECT" pour choisir la fonction du système du moniteur et "ENTER" pour accéder et visualiser les paramètres surveillés. Employez la clé "SELECT" pour changer la révision de logiciel, la quantité d'heures de travail faites et de la quantité de cycles complets exécutés depuis la première initialisation.


This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.




250




300




350/350D




380A




450T




400A




450A



550A




420A




600A




VACUUM PACKAGING MACHINES




620A




650A



680A



700A



750A