


WIRING DIAGRAM / ESQUEMA ELECTRICO



- 1 Switch
- 2 5-125°C (32-248F) Thermostat
- 3 Limit switch 152°C (305.6F)
- 4 Resistance
- 5 5-95°C (32-194F) Thermostat
- 6 Gear motor

- Interrupor
Termóstato 5-125°C (32-248F)
Fusible de seguridad 152°C (305.6F)
Resistencia
Termóstato 5-95°C (32-194F)
Motoreductor