

SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC PACKAGED AIR-CONDITIONERS

**Series : PQRYP•THMU-A
PQRYP•YHMU-A**

REVISED

Aug. 2012

BWE0926B

INDEX

**PQRYP72THMU-A
PQRYP96THMU-A
PQRYP120THMU-A
PQRYP72YHMU-A
PQRYP96YHMU-A
PQRYP120YHMU-A**

The Package name list

PQRYP144TSHMU-A	[PQRYP72THMU-A+PQRYP72THMU-A]
PQRYP168TSHMU-A	[PQRYP72THMU-A+PQRYP96THMU-A]
PQRYP192TSHMU-A	[PQRYP96THMU-A+PQRYP96THMU-A]
PQRYP216TSHMU-A	[PQRYP96THMU-A+PQRYP120THMU-A]
PQRYP240TSHMU-A	[PQRYP120THMU-A+PQRYP120THMU-A]
PQRYP144YSHMU-A	[PQRYP72YHMU-A+PQRYP72YHMU-A]
PQRYP168YSHMU-A	[PQRYP72YHMU-A+PQRYP96YHMU-A]
PQRYP192YSHMU-A	[PQRYP96YHMU-A+PQRYP96YHMU-A]
PQRYP216YSHMU-A	[PQRYP96YHMU-A+PQRYP120YHMU-A]
PQRYP240YSHMU-A	[PQRYP120YHMU-A+PQRYP120YHMU-A]


Part information update day : **2012/08/24**

Please change the old catalog (issued Nov. 2010, No.BWE0926A) to this new catalog.
Content of revision : Some of parts are changed.




PQRY-P72,P96,P120THMU-A
PQRY-P72,P96,P120YHMU-A

EXTERNAL PARTS



[illegible]




*1 Check valve (217) alone can be replaced only if it is accessible from behind the unit; otherwise, the entire check valve assembly (218) needs to be replaced.


PQRY-P72,P96,P120THMU-A
PQRY-P72,P96,P120YHMU-A

FUNCTIONAL PARTS

[illegible]



6



8

mitsubishi electric corporation
HEAD OFFICE: TOKYO BLDG., 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN

BWE0926B (20120831)