


WIRING DIAGRAM

- 14 GA. AWM-105°C
- ▲ 14 GA. TFE-200°C
- 16 GA. AWM-105°C
- * 16 GA. TFE-200°C
- △ 22 GA. AWM-105°C
- # 18 GA. AWM-105°C



WIRING DIAGRAM

- 4 GA. AWM-105°C
- ▲ 14 GA. TFE-200°C
- 16 GA. AWM-105°C
- * 16 GA. TFE-200°C
- △ 22 GA. AWM-105°C
- # 18 GA. AWM-105°C

