



Wiring Diagram - SM-6695H

Item	Part #	Description	Item	Part #	Description	Item	Part #	Description	Item	Part #	Description
M1	3.3.01.07.003	Motor - 600W	M6	3.3.01.01.001	HA Motor	S3	3.1.03.03.002	Power Switch	S10	3.1.01.07.003	Thermostat - C
M2	3.2.01.02.005	Compressor - Main	KM	3.1.01.01.010	Contactors	S4	3.1.03.01.004	Draw Switch	S11	3.1.03.04.015	Standby Switch
M3	3.2.03.04.001	Fan Motor - Main	JR	3.1.01.02.010	Thermal Relay	S5	3.1.03.04.009	Low Mix Sensor	LAMP	3.1.02.14.001	Low Mix Light
M4	3.2.01.01.002	Compressor - Aux	T	3.1.01.04.007	Transformer	S8	3.1.03.02.002	Torque Switch	BELL	3.1.02.15.003	Low Mix Alarm
M5	3.2.03.01.001	Fan Motor - Aux	S1/2	3.2.04.06.004	Pressure Switch	S9	3.1.01.07.003	Thermostat - H	PCB	2.1.1.30.0012	Control Board