


## E2 Enclosure



## E1 Enclosure



**Wiring Diagram - SM-6795H**

Item	Part #	Description	Item	Part #	Description	Item	Part #	Description
M1	3.3.01.07.003	Motor - 600W	M6	3.3.01.01.001	HA Motor	S4	3.1.03.01.004	Draw Switch
M2	3.2.01.02.005	Compressor - Main	KM	3.1.01.01.010	Contactors	S5	3.1.03.04.009	Low Mix Sensor
M3	3.2.03.04.001	Fan Motor - Main	JR	3.1.01.02.010	Thermal Relay	S8	3.1.03.02.002	Torque Switch
M4	3.2.01.01.002	Compressor - Aux	T	3.1.01.04.005	Transformer	S9	3.1.01.07.003	Thermostat-H
M5	3.2.03.01.001	Fan Motor - Aux	S1/2	3.2.04.06.004	Pressure Switch	S10	3.1.01.07.003	Thermostat - C
						PCB	2.1.1.30.0012	Control Board