

DMS-72, -96 SERIES ONLY

DEFROST SETTINGS  
2 DEFROSTS/DAY  
50 MINUTE FAIL SAFE


TEMPERATURE CONTROL SETTINGS




COLD CUT OUT - 5°F  
COLD CUT IN - 21°F




WARM CUT OUT - 42°F  
WARM CUT IN - 52°F



115/60/1  
NEMA 5-15P



DMS-96 SERIES



DMS-48, -72 SERIES

DMS -72, -96 SERIES ONLY

DEFROST SETTINGS  
3 DEFROSTS/DAY  
60 MINUTE FAIL SAFE



TEMPERATURE CONTROL SETTINGS



COLD CUT OUT - 5°F  
COLD CUT IN - 21°F



WARM CUT OUT - 42°F  
WARM CUT IN - 52°F





FIELD WIRING

115/60/1


DMS-72, -96 SERIES ONLY

DEFROST SETTINGS  
2 DEFROSTS/DAY  
50 MINUTE FAIL SAFE


TEMPERATURE CONTROL SETTINGS



115/60/1  
NEMA 5-15P



DMS-96 SERIES



DMS-48, -72 SERIES

DMS-72, -96 SERIES ONLY

DMS-48 SERIE ONLY

DEFROST SETTINGS  
2 DEFROSTS/DAY  
50 MINUTE FAIL SAFE



TEMPERATURE CONTROL SETTINGS




COLD CUT OUT - 5°F  
COLD CUT IN - 21°F



WARM CUT OUT - 42°F  
WARM CUT IN - 52°F



DMS-96 SERIES



DMS-48, -72 SERIES